

General Environmental Incident Summary

Incident: 2170 **Date/Time Notice:** 1/10/2014 1914 **DEM Incident No:**

Responsible Party: unknown

Date Incident: 1/8/2014

Time Incident:

Duration:

County: Mountrail **Twp:** 156 **Rng:** 93 **Sec:** 9 **Qtr:** SE SE

Lat: 48.34292 **Long:** -102.63410 **Method:** Navigation quality GPS

Location Description: Ross, ND near Hess H. Juma 1-9H wellpad

Submitted By: Scott Stockdill

Affiliation:

Address: 918 E. Divide Ave

City: Bismarck

State: ND

Zip:

Received By:

Contact Person:

Unknown

Unknown, ND

Distance Nearest Occupied Building: 2000 Feet

Type of Incident: Tank Leak

Description of Released Contaminant: #2 Diesel Fuel

Volume Spilled: 30.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Unknown

Risk Evaluation:

None

of Fatalities: 0

of Injuries: 0

Affected Medium: 04 - water and soil

Potential Environmental Impacts:

Contaminant can possible kill nearby vegetation and impact ground and surface waters

Action Taken or Planned:

None

Wastes Disposal Location: Unknown

Agencies Involved:

Updates

Date: 1/10/2014 **Status:** Inspection

Author: Stockdill, Scott

Updated Volume:

Notes:

Arrived on location 11:25 1/09/14.

Came across diesel spill along county road near H.Juma 1-9H well pad. No cleanup has occurred.

Followup is necessary. Hess will be contacted during the week of 1/13/14 to determine if they were responsible for said spill. A request will be made for them to clean up the spill.

Date: 1/10/2014 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Volume:

Notes:

Followup required.

Date: 5/12/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Volume:

Notes:

Arrived on location at 13:30 5/12/2015.

Impacted gravel road has been paved, and there are no lingering effects of the spill at that location.

No followup is necessary.